AT-180 Tuner Not Matching on 60 Meters

Category: HF Operation
November 27, 2021
An internal tuner is limited in what it can do.